

Headquarter Address: 8F.No.33, Lane 155, Sec.3, Bei-Shen Rd., Shen Keng Dist, New Taipei City, Taiwan

TEL: +886-2-26620988 FAX: +886-2-26620488

Product/Process Change Notification

PCN#	Effective Date		Issue Date			
2014-06-20C-01	2014/8/1		2014/6/20			
PCN Classification		Product Category				
Minor		1206 Package				
Subject						
Tapping Changed						
Affected Product(s)						
Product list as attachment						
Description of Change(s)						
The reason we changed carry tap is to prevent the material attached.						
Content of Change(s)						
Changed the tap, the reel size is still the same.						
Impact(s)						
N/A						
Attachment(s)						
None						

Approval					
Issue by	Alice Lai	e-mail: alice@secosgmbh.com			
Development Engineer	A	Alice Lai			
QA Manager		Peter Yang			
General Manger		Mathew Liu			

Unless customer has specific concerns and further notice, otherwise this product change notice will be deemed to agree the change. For more information, please contact us directly or visit our website http://www.secosgmbh.com



Headquarter Address: 8F.No.33, Lane 155, Sec.3, Bei-Shen Rd., Shen Keng Dist, New Taipei City, Taiwan

TEL: +886-2-26620988 FAX: +886-2-26620488

Affected Product List

SSCD102	SSCD104L	SCDF105	SCDH103
SSCD104	SCD5392	SCDF106	SCD5391
SSCD106	SCD5393	SCDF107	SCDH104
SSCD110	SCD5395	SCDS101	SCDH105
SSCD202	SCD5397	SCDS102	SCDH106
SSCD204	SCD5398	SCDS103	SCDH107
SSCD206	SCD5399	SCDS104	
SSCD210	SCDF103	SCDS105	
SSCD102L	SCDF104	SCDS106	




Headquarter Address: 8F.No.33, Lane 155, Sec.3, Bei-Shen Rd., Shen Keng Dist, New Taipei City, Taiwan

TEL: +886-2-26620988 FAX: +886-2-26620488

Exterior comparison Chart

Original package




Top View



Top View



Lateral View



Lateral View



Reel



Reel